Map ID MAP FINDINGS

Direction Distance

Distance EDR ID Number
Elevation Site EDR ID Number

EM715 PVT DWELLING NY Spills S110045017
North 195 AVE V N/A

> 1 BROOKLYN, NY

1.010 mi.

5335 ft. Site 2 of 2 in cluster EM

 Relative:
 SPILLS:

 Higher
 Name:
 PVT DWELLING

 Actual:
 Address:
 195 AVE V

 18 ft.
 City,State,Zip:
 BROOKLYN, NY

 Spill Number/Closed Date:
 0909020 / 2010-07-26

 Facility ID:
 0909020

 Facility Type:
 ER

 DER Facility ID:
 370636

 Site ID:
 421687

 DEC Region:
 2

Spill Cause: Equipment Failure

Spill Class: D4 SWIS: 2401 Spill Date: 2009-11-11 Investigator: **RMPIPER** Referred To: Not reported Reported to Dept: 2009-11-11 CID: Not reported Water Affected: Not reported Spill Source: Private Dwelling Spill Notifier: Affected Persons Cleanup Ceased: Not reported Cleanup Meets Std: False Last Inspection: Not reported Recommended Penalty: False **UST Trust**: False Remediation Phase: 0

Date Entered In Computer: 2009-11-11
Spill Record Last Update: 2010-07-26
Spiller Name: Not reported

Spiller Company: DIANN BENESSERE

Spiller Address: Not reported

Spiller Company: 999

Contact Name: DIANN BENESSERE

DEC Memo: "DECPiper performed site visit. Tank has slow leak in bottom. Milro

pumped it out and set up temp tank. Area needs to be cleanened and epoxy painted. 7/26/10- DEC Piper- Small spill to concrete basement.

Spill closed."

Remarks: "275 gal indoor tank/repairs underway/spill contained"

All Materials:

Site ID: 421687 Operable Unit ID: 1177570 Operable Unit: 01 Material ID: 2170372 Material Code: 0001A Material Name: #2 fuel oil Case No .: Not reported Material FA: Petroleum Quantity: Not reported

Units: G
Recovered: Not reported
Oxygenate: Not reported